

الهيئة العامة للطيران المدني  
GENERAL CIVIL AVIATION AUTHORITY



# Air Accident Investigation Sector

## Accident

### - Second Interim Statement -

AAIS Case N°: AIFN/0008/2016

# Runway Impact During Attempted Go-Around

Operator:	Emirates Airline
Make and Model:	Boeing 777-31H
Nationality and Registration:	The United Arab Emirates, A6-EMW
Place of Occurrence:	Dubai International Airport
State of Occurrence:	The United Arab Emirates
Date of Occurrence:	3 August 2016



## Occurrence Brief

Occurrence Reference	:	AIFN/0008/2016
Occurrence Category	:	Accident
Name of the Operator	:	Emirates Airline
Manufacturer	:	The Boeing Company
Aircraft Model	:	777-31H
Engines	:	Two Rolls-Royce Trent 892
Nationality	:	The United Arab Emirates
Registration	:	A6-EMW
Manufacture Serial Number	:	32700
Date of Manufacture	:	27 March 2003
Flight Hours/Cycles	:	58,169/13,620
Type of Flight	:	Scheduled Passenger
State of Occurrence	:	The United Arab Emirates
Place of Occurrence	:	Runway 12L, Dubai International Airport
Date and Time	:	3 August 2016, 0837 UTC
Total Crewmembers	:	18 (two flight and 16 cabin)
Total Passengers	:	282
Injuries to Passengers and Crew	:	32 (four serious, 28 minor)
Other Injuries	:	One Firefighter (fatal)
Nature of Damage	:	The Aircraft was destroyed

## Investigation Objective

This Investigation is performed pursuant to the United Arab Emirates (UAE) *Federal Act No. 20 of 1991*, promulgating the *Civil Aviation Law, Chapter VII – Aircraft Accidents*, Article 48. It is in compliance with Part VI, Chapter 3 of Part VI, Chapter 3, of the *Civil Aviation Regulations (CARs)* of the United Arab Emirates, and in conformity with *Annex 13* to the Convention on International Civil Aviation.

The sole objective of this Investigation is to prevent aircraft accidents and incidents. It is not the purpose of this activity to apportion blame or liability.

This second anniversary Interim Statement gives a brief of the Investigation progress and should be read in conjunction with the Preliminary Report number AIFN/0008/2016 that was published on 5 September 2016.



This Interim Statement is released in accordance Standard 6.6 of ICAO *Annex 13* and paragraph 7.4 of UAE CAR Part VI, Chapter 3.

Later Interim Statements/Reports, or the Final Report, may contain altered information in case of new evidence becoming available during the ongoing investigation.

## Investigation Process

The occurrence was classified as an Accident and the Air Accident Investigation Sector (AAIS) of the United Arab Emirates assigned an Accident Investigation File Number AIFN/0008/2016 for the case.

The AAIS formed the Investigation team led by the investigator-in-charge (IIC) and members from the AAIS for the relevant investigation aspects. The National Transportation Safety Board (NTSB) of the United States, being the State of the Manufacture and Design, and the Air Accidents Investigation Branch (AAIB) of the United Kingdom, being the State of Manufacture of the engines, were notified of the Accident and both States assigned Accredited Representatives assisted by Advisers from Boeing and Rolls-Royce. In addition, the Operator assigned an Adviser to the IIC. The AAIS is leading the Investigation and will issue a Final Report.

This Interim Statement is publicly available at:

<http://www.gcaa.gov.ae/en/epublication/pages/investigationReport.aspx>



## Second Interim Statement

This second anniversary Interim statement gives a brief account of the progress of the Investigation into the subject Accident. The statement is released in accordance Standard 6.6 of ICAO Annex 13 and paragraph 7.4 of UAE CAR Part VI, Chapter 3.

The Accident occurred on 3 August 2016 and involved an Emirates Airline Boeing 777-300 aircraft, registration A6-EMW, operating a scheduled passenger flight EK521, that had departed Trivandrum International Airport (VOTV), India, at 0506 UTC for Dubai International Airport (OMDB), the United Arab Emirates. At approximately 0837:38 UTC, the Aircraft impacted runway 12L during an attempted go-around at OMDB.

The Aircraft sustained substantial structural damage as a result of the impact and its movement along the runway and was eventually destroyed by fire. Twenty-one passengers, one flight crewmember, and six cabin crewmembers sustained minor injuries. Four cabin crewmembers sustained serious injuries. Approximately nine minutes after the Aircraft came to rest, a firefighter was fatally injured as a result of the explosion of the center wing fuel tank.

As stated in the first interim statement issued on 6 August 2017, the Investigation is completed into the specific areas of interest including flight operations, human performance, training standards, procedures, aircraft systems, passenger evacuation, oversight and airport emergency response.

An Annex 13 format draft final report has been issued which documents the details of findings, and cause and contributory factors to the Accident. Improvements identified in the areas of interest will be addressed to the concerned organizations as safety recommendations.

Currently, the UAE GCAA Air Accident Investigation Sector, has started the draft final report review process in accordance with the AAIS internal procedures. A consultation review, as per Annex 13, will also involve the concerned State authorities, Emirates Airline and other organizations. Feedback to the draft final report will include comments and safety actions taken.

The Final Report will be published after the AAIS has addressed the comments received by either amending the Report and/or appending disagreed comments.

This second Interim statement is issued by:

The Air Accident Investigation Sector

General Civil Aviation Authority

The United Arab Emirates

P.O. BOX 6558, Abu Dhabi.

Email: [aaig@gcaa.gov.ae](mailto:aaig@gcaa.gov.ae)