



## Information Bulletin Number 05/2001

**To** : Mr. Khaled Ghaith Al Muhairbi, Director, Abu Dhabi International Airport,  
P.O. Box 20, Abu Dhabi, U.A.E. Fax: 5757228

**From** : Acting Director Flight Safety Services

**Ref.** : 20212/0671/01 **Date** : 12 August 2001

**Subject** : **Transponder Policy**

**CC** : H.E. Abdulla Saeed Al Hameli, Assistant Undersecretary, DCA, Abu Dhabi  
Fax: 02-5757788; Director Air Navigation Services, GCAA; Emirates Area  
Control (GCAA)

This Information Bulletin is intended to direct your attention to UAE Aeronautical Information Circular (AIC) number 03 dated 10 February 2001, (attached) on “**Action taken in the event of unserviceable transponder**”.

Please be informed that following procedures are to be taken before recommending release of grounded aircraft with unserviceable transponders.

1. Rectification of the defect by the operator.
2. In case of replacement of the antenna or the transponder the following must be recorded.
  - (a) Part number OFF/ON
  - (b) Serial number OFF/ON
3. Test flight is required to confirm serviceability of Transponder that is not equipped to be activated on ground.
4. Confirmation from the ATC units of the respective airports (DCA's) to Emirates Area Control Centre (GCAA) of the result of Item 3 above.
5. Physical inspection of the aircraft by GCAA inspector remains optional depending on the circumstances.
6. When the above are satisfactory, Flight Safety Services of General Civil Aviation Authority shall release the aircraft either by verbal authorisation to Emirates Area Control Centre or by written authorisation to respective Department of Civil Aviation.

Kindly advice all concerned.

Regards,

  
AHMED AL HADDABI

Attachment: AIC No: 03 (2001)

UNITED ARAB EMIRATES  
GENERAL CIVIL AVIATION AUTHORITY



دولة الإمارات العربية المتحدة  
الهيئة العامة للطيران المدني

## Information Bulletin Number 05/2001

**To** : Mr. Mohammed Abdullah Ahli, Director of Operations, Department of Civil Aviation, P.O. Box 2525, Dubai, Fax: 04 2244502

**From** : Acting Director Flight Safety Services

**Ref.** : 20212/0671/01 **Date** : 12 August 2001

**Subject** : **Transponder Policy**

**CC** : H.H. Sh. Ahmed Bin Saeed Al Maktoum, President DCA & Chairman Emirates Department of Civil Aviation, P.O. Box 2525, Dubai, Fax: 04-2244074; Director Air Navigation Services, GCAA; Emirates Area Control (GCAA)

This Information Bulletin is intended to direct your attention to UAE Aeronautical Information Circular (AIC) number 03 dated 10 February 2001, (attached) on "Action taken in the event of unserviceable transponder".

Please be informed that following procedures are to be taken before recommending release of grounded aircraft with unserviceable transponders.

1. Rectification of the defect by the operator.
2. In case of replacement of the antenna or the transponder the following must be recorded.  
(c) Part number OFF/ON  
(d) Serial number OFF/ON
3. Test flight is required to confirm serviceability of Transponder that is not equipped to be activated on ground.
4. Confirmation from the ATC units of the respective airports (DCA's) to Emirates Area Control Centre (GCAA) of the result of Item 3 above.
5. Physical inspection of the aircraft by GCAA inspector remains optional depending on the circumstances.
6. When the above are satisfactory, Flight Safety Services of General Civil Aviation Authority shall release the aircraft either by verbal authorisation to Emirates Area Control Centre or by written authorisation to respective Department of Civil Aviation.

Kindly advice all concerned.

Regards,

  
AHMED AL HADDABI

Attachment: AIC No: 03 (2001)



## Information Bulletin Number 05/2001

**To** : Dr. Ghanem Al Hajri, Director General, Sharjah Airport Authority, P.O. Box 8, Sharjah, Fax: 06 5581167

**From** : Acting Director Flight Safety Services

**Ref.** : 20212/0671/01 **Date** : 12 August 2001

**Subject** : **Transponder Policy**

**CC** : H.E. Mohammad Saif Al Hajri, Director General, Department of Civil Aviation, P.O. Box 8, Sharjah, Fax: 06-5580880; Director Air Navigation Services, GCAA; Emirates Area Control (GCAA)

This Information Bulletin is intended to direct your attention to UAE Aeronautical Information Circular (AIC) number 03 dated 10 February 2001, (attached) on “**Action taken in the event of unserviceable transponder**”.

Please be informed that following procedures are to be taken before recommending release of grounded aircraft with unserviceable transponders.

1. Rectification of the defect by the operator.
2. In case of replacement of the antenna or the transponder the following must be recorded.  
(e) Part number OFF/ON  
(f) Serial number OFF/ON
3. Test flight is required to confirm serviceability of Transponder that is not equipped to be activated on ground.
4. Confirmation from the ATC units of the respective airports (DCA's) to Emirates Area Control Centre (GCAA) of the result of Item 3 above.
5. Physical inspection of the aircraft by GCAA inspector remains optional depending on the circumstances.
6. When the above are satisfactory, Flight Safety Services of General Civil Aviation Authority shall release the aircraft either by verbal authorisation to Emirates Area Control Centre or by written authorisation to respective Department of Civil Aviation.

Kindly advice all concerned.

Regards,

  
AHMED AL HADDABI

**Attachment: AIC No: 03 (2001)**

UNITED ARAB EMIRATES  
GENERAL CIVIL AVIATION AUTHORITY



دولة الإمارات العربية المتحدة  
الهيئة العامة للطيران المدني

## Information Bulletin Number 05/2001

**To** : Mr. Khaled Al Mazroui, General Manager, Fujairah International Airport, P.O. Box 977, Fujairah, Fax: 09 2241414  
**From** : Acting Director Flight Safety Services  
**Ref.** : 20212/0671/01 **Date** : 12 August 2001  
**Subject** : **Transponder Policy**  
**CC** : Mr. H.E. Mohammed Abdulla Al Salami, Chairman, Department of Civil Aviation, P.O. Box 977, Fujairah, Fax: 09-2227229; Director Air Navigation Services, GCAA; Emirates Area Control (GCAA)



This Information Bulletin is intended to direct your attention to UAE Aeronautical Information Circular (AIC) number 03 dated 10 February 2001, (attached) on “**Action taken in the event of unserviceable transponder**”.

Please be informed that following procedures are to be taken before recommending release of grounded aircraft with unserviceable transponders.

1. Rectification of the defect by the operator.
2. In case of replacement of the antenna or the transponder the following must be recorded.
  - (i) Part number OFF/ON
  - (j) Serial number OFF/ON
3. Test flight is required to confirm serviceability of Transponder that is not equipped to be activated on ground.
4. Confirmation from the ATC units of the respective airports (DCA's) to Emirates Area Control Centre (GCAA) of the result of Item 3 above.
5. Physical inspection of the aircraft by GCAA inspector remains optional depending on the circumstances.
6. When the above are satisfactory, Flight Safety Services of General Civil Aviation Authority shall release the aircraft either by verbal authorisation to Emirates Area Control Centre or by written authorisation to respective Department of Civil Aviation.

Kindly advice all concerned.

Regards,

  
  
**AHMED AL HADDABI**

**Attachment: AIC No: 03 (2001)**



## Information Bulletin Number 05/2001

**To** : Mr. Mohamed Al Kadar, Operations Director, Department of Civil Aviation, P.O. Box 5214, Ras Al Khaimah, Fax: 07 2448199

**From** : Acting Director Flight Safety Services

**Ref.** : 20212/0671/01 **Date** : 12 August 2001

**Subject** : **Transponder Policy**

**CC** : H.H. Sh. Salem Bin Sultan Al Qasimi, Chairman, Department of Civil Aviation, P.O. Box 5214, Ras Al Khaimah, Fax: 07-244886; Director Air Navigation Services, GCAA; Emirates Area Control (GCAA)

This Information Bulletin is intended to direct your attention to UAE Aeronautical Information Circular (AIC) number 03 dated 10 February 2001, (attached) on “**Action taken in the event of unserviceable transponder**”.

Please be informed that following procedures are to be taken before recommending release of grounded aircraft with unserviceable transponders.

1. Rectification of the defect by the operator.
2. In case of replacement of the antenna or the transponder the following must be recorded.  
(g) Part number OFF/ON  
(h) Serial number OFF/ON
3. Test flight is required to confirm serviceability of Transponder that is not equipped to be activated on ground.
4. Confirmation from the ATC units of the respective airports (DCA's) to Emirates Area Control Centre (GCAA) of the result of Item 3 above.
5. Physical inspection of the aircraft by GCAA inspector remains optional depending on the circumstances.
6. When the above are satisfactory, Flight Safety Services of General Civil Aviation Authority shall release the aircraft either by verbal authorisation to Emirates Area Control Centre or by written authorisation to respective Department of Civil Aviation.

Kindly advice all concerned.

Regards,



**AHMED AL HADDABI**

**Attachment: AIC No: 03 (2001)**