

FLIGHT TRACK PLAN




Fig 1

OVERRUN




Fig 2

ACCIDENT SITE



NO 2 NACELLE VIEWED FROM CABIN WINDOW



Fig 3

HS748 GENERAL LAYOUT




Fig 4

FUEL HEATER




Fig 5

DART ENGINE SCHEMATIC




Fig 6

COMBUSTION CHAMBER






Fig 7

FUEL BURNER SCHEMATIC



SWIRL CHAMBER

TURBINE ASSEMBLY




Fig 9

HP TURBINE DISC




Fig 10

G-OJEM'S NO 2 ENGINE HP TURBINE DISC PORTION



Fig 11

G-OJEM'S NO 2 ENGINE HP TURBINE DISC
FRACTURE SURFACE




Fig 12